

## Third Floor Classroom Addition

Scaffolding in place for old roof removal and installation of new exterior brick wall and windows



## New two Story Administration Addition

Exterior Sheathing in place, Brick and Windows to follow. Roof Structure for Acoustical Screen in place.





## **First Floor Administration Addition**

Exterior Steel Stud wall in place,  
Ductwork, Plumbing, Sprinkler and  
Electrical work in progress.